

PROPOSAL Marsh Landing Repair List

April 22, 2024

Job Description: Repairs

- ❖ Bldg. 1- ok
- Bldg. 2- Southside between kitchen window and entryway soffit has slight opening.
- ❖ Bldg. 3-Southside soffit hanging loose between kitchen window and side door.
- ❖ Bldg. 4- South side between kitchen and entryway door soffit was replaced but cut short and has gap.
- ❖ Bldg. 4- fascia in the back by 22966 MBR window in lanai is cut short and leaves about half inch gap.
- ❖ Bldg. 4- entryway of 22968 soffit is lifted and leaves a gap near rain gutter.
- ❖ Bldg. 5- upper South aide unit has a hole in trim with birds living in it.
- ❖ Bldg. 5- 22934 north side piece popping out.
- ❖ Bldg. 12- South aide soffit replaced but has a gap.
- ❖ Bldg. 13- looked ok.
- ❖ Bldg. 14- hold on Southeast aide (22989)
- Bldg. 15- Nothing

Total Cost: \$535.00

Acceptance of Proposal: The above prices and specifications are satisfactory and are hereby accepted.

Signature

Date: 4-29-24